ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0630, W1141, W1109	NA	Markandaiahnagara
Segment No.	**Total Length (m)**	
5/C-W0630/S030322	260.59	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	134.33	77.631681	13.097942	77.632211	13.099040	Markandaiahnagara	main road
2	126.26	77.629652	13.098794	77.630159	13.099821	Markandaiahnagara	1st cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road and drains at Markandaiahnagara, Agrahara layout cross roads in ward no. 05 Byatarayanapura sub division.	2500000	2013-14
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender		005-14-000050
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/592/2013-14	03/03/2014	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
20/11/2018	20/11/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B.R.Dhananjaya		0.00
Phone No.	**E-Mail ID**	
9591739363		

Field Inspection Details

Number of Trees

0

Any Other Information

Name

mahantesh kumar

Date of Inspection

27/11/2018

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0630, W1141, W1109